

Enclosure to Lr.No. EE/CD/DB/D1/2024-25/ Dated. 04.02.2025

BUILDING SAFETY CERTIFICATE

Certified that the existing building **SHREE SWAMINARAYAN GURUKUL VIDYALAYA (SCHOOL BLOCK A,B AND C) AT Enkepally Chevella Road Enkapally P.O, Moinabad Mandal, Rangareddy District TELANGANA-500075 comprised of G+4 (floors) owned by SHREE SWAMI NARAYANGURUKUL, Hyderabad (Trust)** have complied with the Building Safety Requirements in accordance with National Building Code/Rules & verified by the officers concerned of **Roads and Buildings** (Name of the Department/Telangana Govt.) on 31.01.2025 in the presence of **Fenil Umaretiya** and that the building/premises is fit for occupancy from Classes I to XII with effect from 04.02.2025 for a period of 1 Year(i.e., 2025-2026) in accordance with rule and subject to compliance of the specific conditions as appended.

Issued on 04.02.2025

Executive Engineer (R&B) Division Chevella, Rangareddy District .

Signature with Seal:

Name:

Designation:

Department:


Executive Engineer
(R & B) Division Chevella,
Rangareddy District, Telangana State.

**GOVERNMENT OF TELANGANA
ROADS & BUILDINGS DEPARTMENT**

From
Sri G. Ravindra Kumar, M.Tech.,
Executive Engineer,
(R&B) Division, Chevella,
Rangareddy District.

To
Shree Swami Narayan Gurukul,
Vidyalaya, Hyderabad,
Chevella Road,
Moinabad Mandal,
Rangareddy District ,
Phone.No. 6354552160.

Lr.No.EE/CD/DB/D1/ 2024-25/ 901 **Dated: 04.02.2025.**

Gentlemen,

Sub: (R&B) Dept- Shree Swami Narayan Gurukul Vidyalaya, Enkepally Village
Moinabad Mandal, Rangareddy District - Structural Soundness Certificate
issued-Regarding.

Ref: 1) Representation of Shree Swami Narayan Gurukul Vidyalaya
RR district Dated.22.01.2025.
2) Dy.EE (R&B) Chevella Sub Division Lr.No.
DEE/Chevella/Building/Soundness/2024-25 Dated.31.01.2025.

With reference to your letter vide reference 1st cited, it is to inform that Shree Swami Narayan Gurukul Vidyalaya located in Enkepally Village, Moinabad Mandal, Rangareddy district was inspected by Deputy Executive Engineer (R&B) Chevella Sub division on 31.01.2025 and reported as below.

The buildings are constructed with RCC Structure. There are no structural drawings submitted to this office along with the letter, Hence the Inspection was done superficially, and the details of the building as observed are mentioned below.

- a. School building Block A, B and C (G+4 Floors)
- b. Painting was done last three Years back.
- c. No Dampness in the External and Internal Walls and Roof Slabs

It is further informed that the, A Prashant Taimale , Certified Licensed Civil Engineer has submitted the structural soundness certificate stating that the

buildings are structurally safe and soundness and followed the relevant IS Code standards and NBC 2005 during construction.

In view of the above, based on the report received from the Deputy Executive Engineer (R&B) Chevella Sub division, the buildings are fit for running the school for a period of **One -year i.e from 04.02.2025 to 03.02.2026.**

Further, it is informed that the school management is completely responsible for taking of the periodical maintenance of the building regularly during this One-year period.

Enclosures: Building Safety Certificate.

Yours Sincerely,


Executive Engineer,
(R&B) Division, Chevella, R.R.Dist.,

Sd/-
04/02/25

Copy to Dy.Executive Engineer(R&B), Sub-Division, Chevella for information and taking necessary action.