

**STRUCTURAL SOUNDNESS & Annexure D**  
**BUILDING SAFETY CERTIFICATE**

No. 05/16.DR, Renigunta.

Dated: 02.05.2025


It is certified that the existing building **SHREE SWAMINARAYAN GURUKUL SCHOOL** at SY NOS.446/3, 447/3, VIKRUTHAMALA VILLAGE, YERPEDU MANDAL, SRIKALAHASTHI DIVISION, TIRUPATI – 517526, ANDHRAPRADESH having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+3	NA	NA	NA	NA	NA

The building is owned/occupied by **SHREE SWAMINARAYAN GURUKUL, Hyderabad** (Trust) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Panbhayala Raj (Name of Department/ Govt.) on 02.05.2025 (date of inspection) in the presence of **Sadhu Vishuddhjivandas** and that the building/premises is fit for occupancy for running school with effect from 02.05.2025 for a period of 3 year years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on ..... at ..... by

  
**Asst. ENGINEER (PRI)**  
**M.P.P., RENIGUNTA.**

Signature with Seal : .....

Name : K. VENKATA RAMANA

Designation : Asst Engineer, PRI

Name & Address of Department/ Office : Renigunta